


## Update Firmware of F-35 Lightning FC

To perform a firmware upgrade perform the following steps (windows only):

1. Install relevant drivers on windows needed to upgrade the F-35 Lightning FC:
  - a. Connect the F-35 Lightning with a USB cable to the computer
  - b. Download and execute the [ImpulseRC Driver Fixer Tool](#)
2. Secure the current configuration by following the instructions on: [NAV upgrade guide](#). In short:
  - a. Use Inav Configurator to connect to the F-35 Lightning FC
  - b. Go to the *CLI* menu and enter `diff all`
  - c. Copy the results to a separate text file
  - d. Manually perform the changes mentioned in the [INAV upgrade guide](#)
3. Execute the firmware update
  - a. Press the *Disconnect* button in the Inav Configurator
  - b. Go to the *Firmware Flasher* menu
  - c. Select **FF F35\_LIGHTNING** as board target
  - d. Select latest firmware version
  - e. Press the *Load Firmware* button
  - f. Press the *Flash Firmware* button



4. Follow the instructions on [INAV upgrade guide](#) to restore the preserved and adjusted configuration from point 2. In short:
  - a. Press the *Connect* button on the Inav Configurator. Once connected you should see the updated firmware version in the upper section.
  - b. Go to the *CLI* menu
  - c. Copy the adjusted settings from the text file mentioned in point 2 and paste them in the *CLI*
  - d. If no errors occur the F-35 Lightning FC reboots itself


## DJI Air Unit

Important notice: The DJI Air Unit requires at least version 2.4.x or higher of INav. By default F-35 Lightning FC is shipped with firmware version 1.9.1. Consequently a firmware update is required. Use the instructions above to perform a firmware version upgrade.

Once the firmware is updated the Air Unit can be configured.


### a) DJI Air Unit with Dji Remote Controller

Identifier	Data	Telemetry	RX	Sensors	Peripherals
USB VCP	<input checked="" type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾
UART1	<input checked="" type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾
UART2	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	GPS ▾ 57600 ▾	Disabled ▾ 115200 ▾
UART3	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input checked="" type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾
UART4	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	IRC Tramp ▾ 115200 ▾
UART5	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	DJI FPV VTX ▾ 115200 ▾
UART6	<input type="checkbox"/> MSP 115200 ▾	SmartPort ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾




b) DJI Air Unit only

Identifier	Data	Telemetry	RX	Sensors	Peripherals
USB VCP	<input checked="" type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾
UART1	<input checked="" type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾
UART2	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	GPS ▾ 57600 ▾	Disabled ▾ 115200 ▾
UART3	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input checked="" type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾
UART4	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	IRC Tramp ▾ 115200 ▾
UART5	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	DJI FPV VTX ▾ 115200 ▾
UART6	<input type="checkbox"/> MSP 115200 ▾	SmartPort ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 115200 ▾	Disabled ▾ 115200 ▾



## R9MM Receiver

Identifier	Data	Telemetry	RX	Sensors	Peripherals
USB VCP	<input checked="" type="checkbox"/> MSP 115200 ▼	Disabled ▼ AUTO ▼	<input type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼
UART1	<input type="checkbox"/> MSP 19200 ▼	Disabled ▼ AUTO ▼	<input type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼
UART2	<input type="checkbox"/> MSP 115200 ▼	Disabled ▼ AUTO ▼	<input type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼
UART3	<input type="checkbox"/> MSP 115200 ▼	Disabled ▼ AUTO ▼	<input checked="" type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼
UART4	<input type="checkbox"/> MSP 115200 ▼	Disabled ▼ AUTO ▼	<input type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼
UART5	<input type="checkbox"/> MSP 115200 ▼	Disabled ▼ AUTO ▼	<input type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼
UART6	<input type="checkbox"/> MSP 115200 ▼	SmartPort ▼ AUTO ▼	<input type="checkbox"/> Serial RX	Disabled ▼ 38400 ▼	Disabled ▼ 115200 ▼




**Important:** For telemetry to work in the latest Inav version (tested with 2.5.x) you have to execute the following command in the CLI menu:

```
set telemetry_halfduplex = OFF
```

As of Inav version 2.5.x this option cannot be set in the User Interface (yet).

## R9Slim+ Receiver

Identifier	Data	Telemetry	RX	Sensors	Peripherals
USB VCP	<input checked="" type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 38400 ▾	Disabled ▾ 115200 ▾
UART1	<input type="checkbox"/> MSP 57600 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 38400 ▾	Disabled ▾ 115200 ▾
UART2	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	GPS ▾ 57600 ▾	Disabled ▾ 115200 ▾
UART3	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input checked="" type="checkbox"/> Serial RX	Disabled ▾ 38400 ▾	Disabled ▾ 115200 ▾
UART4	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 38400 ▾	IRC Tramp ▾ 115200 ▾
UART5	<input type="checkbox"/> MSP 115200 ▾	Disabled ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 38400 ▾	Disabled ▾ 115200 ▾
UART6	<input type="checkbox"/> MSP 115200 ▾	SmartPort ▾ AUTO ▾	<input type="checkbox"/> Serial RX	Disabled ▾ 38400 ▾	Disabled ▾ 115200 ▾



**Important:** For telemetry to work in the latest Inav version (tested with 2.5.x) you have to execute the following command in the CLI menu:

```
set telemetry_halfduplex = OFF
```

As of Inav version 2.5.x this option cannot be set in the User Interface (yet).